



ecology and environment, inc.

111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-663-9415

International Specialists in the Environment

REFERENCE 26
SITE NAME Alton Mun. L.F.
SITE ID ILD980497614
ILD335-06

M E M O R A N D U M

EPA Region 5 Records Ctr.



288706

DATE: November 13, 1986
TO: File
FROM: Kelly Walker *Kul*
SUBJECT: Illinois/F05-8611-025/ILD335HR
Alton/Alton Municipal Landfill
ILD980497614

On November 12, 1986, the author met with Nickolas J. Longo, the chief inspector during the FIT site inspection conducted at this site on November 15, 1984, and the sampling mission on January 10, 1985. Mr. Longo designated on the topographic (Ref. 14) the location of the on-site ditch, leachate sample collected on January 10, 1985, active fill area, filled area, wooded area, and the site entrance road. He stated that the abandoned railroad, which appears on the topographic map (Ref. 14), is not visible. He estimated the facility slope of the active working face to be approximately 10% and the terrain average slope to be approximately 1%. These slope estimations are based on site conditions at the time of Mr. Longo's visits mentioned above. Mr. Longo currently is employed by the U.S. EPA and can be reached in the Enforcement Section at (312) 886-4746.

44E:5X